

ABC, INC. – RESTAURANT SITE PHOTO LOG – 12/06/18



Pic 1.1: Looking west at east entrance with minor cracking observed



Pic 1.2: Looking at building entrance and ADA parking



Pic 1.3: Crosswalk at shared entrance to Watson Rd



Pic 1.4: Crosswalk at east entrance